

Report No.

WP-19057491-JC-01 EnR1

Drain Channel Cover

Sample Name

Entrusted Inspection

Sample Origin

Client

Hangzhou Moonbay Industrial Co., Ltd.





Report No.: WP-19057491-JC-01 EnR1

微谱技术

Page No.: 1/6

Name of Sample	Drain Channel Cover				
Number	/	Specification	/		
Description of Sample	Solid	Lot No./Type	/		
Client	Hangzhou Moonbay Industrial Co., Ltd				
Client Address	703 Building 2, Zhongdong International Plaza, Fengqing Avenue, Xiaoshan, Hangzhou, China				
Sampling Date	/	Sample Receiving Date	2019-06-06		
Test Date	2019-06-06~2019-06-17				
Test Item(s), Criterion(s) and Result(s)	Please see the next page(s)				
Note(s)	This Report cancels and supersedes the Report No·WP-19057491-JC-01En issued by Microspectrum Technology Co., Ltd, original report will be invalid from today.				

Compiled by:

Wen Liang Li ly

Inspected by:

Lily

Issued Date:

2019-06-27

服务电话 Tel: 400-776-7627

Approved by:

Address: Building 9, Building 10, Building 18, Urban Industrial Park, Lane 139, Guowei Road, Yangpu District, Shanghai 官方网址 Web: www.weipujishu.com



Report No.: WP-19057491-JC-01 EnR1

Page No.: 2/6

#### 1. Test Result(s):

Sample No.	Sample Name	Test Item	Test Result	Unit	Test Criterion
19062687-1	Drain Channel Cover	Bearing test	4316N (440kg)	/	Designated by customer

#### Note(s):

1. Examination condition : Test platen diameter : 150mm ; Velocity : 5mm/min;

2. Only one set of sample was provided by the customer , the results are for reference only.

\*\*\* End of the Page \*\*\*

服务电话 Tel: 400-776-7627 Address: Building 9, Building 10, Building 18, Urban Industrial Park, Lane 139, Guowei Road, Yangpu District, Shanghai 官方网址 Web: www.weipujishu.com



Report No.: WP-19057491-JC-01 EnR1

#### 2. Typical Attachment(s):




Fg.1 Picture of sample before load-bearing test
\*\*\* End of the Page \*\*\*

Page No.: 3/6



Report No.: WP-19057491-JC-01 EnR1

Page No.: 4/6



Fg.2 Picture of sample during load-bearing test
\*\*\* End of the Page \*\*\*



Report No.: WP-19057491-JC-01 EnR1

Fg. 3 Picture of sample after load-bearing test \*\*\* End of the Page \*\*\*

Page No.: 5/6



Report No.: WP-19057491-JC-01 EnR1

#### 3. Sample Picture(s):

Page No.: 6/6

服务电话 Tel: 400-776-7627



\*\*\* End of the Report \*\*\*

#### **DECLARE:**

1. The report is invalid without the stamp of special seal for report or without the signature of the compiler, the inspector and the approver.

2. No unauthorized changes, additions or deletions shall be made to the report.

3. Neither fragmented report nor its incomplete copy shall be deemed valid. The complete copy is invalid without the stamp of special seal for report.

4. Any queries on the report shall be presented to Microspectrum Technology Co., Ltd. within 15 working days after receipt of the report.

5. The results described here in this report are based on the sample(s) tested. The results are presented to the client for internal uses only and do not constitute any social grounds in the People's Republic of China.

6. The client takes full responsible for the truthfulness of the testing sample(s) and information related thereto.